

FIG. 1




FIG. 2

Title: Handling Execptions
Inventor: Rajeev Grover et al.
USPTO App. No.: not yet assigned
HP PDNO: 200300624-1

3/4

,	Task Name	Exception Type	Action	Parameters	Dependencies
310	User interface	Undefined instructions	Restart	Initial stack size, task priority	LAN monitor task
320	Telnet session	Software interupt	Cleanup then Restart	Port number, initial stack size, task priority	LAN monitor task, command handler task, LAN hardware
330	HTTP deamon	Data abort	Terminate	None	None
340	LAN monitor	Data abort	Reset LAN hardware	LAN register base address, operating mode	None
350	Console routing	Software interupt	Reset system	None	None
:	•	•	•	•	
•	•	•	•	•	•

<u>G</u>.3

300

Title: Handling Execptions
Inventor: Rajeev Grover et al.
USPTO App. No.: not yet assigned
HP PDNO: 200300624-1

